



**BRIDGESTONE AUSTRALIA LTD.**

ABN 65 007 516 841

**HEAD OFFICE**

Level 1  
196 Greenhill Road  
Eastwood 5063 South Australia

Postal Address - GPO Box 2200  
Adelaide 5001 South Australia

Telephone (08) 8206 0200  
Facsimile (08) 8206 0299  
E-mail [headoffice@bsal.com.au](mailto:headoffice@bsal.com.au)

September 2017

Dear Local Resident

**Groundwater Contamination Investigations – Edwardstown**

As you may be aware, the Environment Protection Authority (EPA) has recently written to residents in your area to commence community engagement on groundwater contamination in Edwardstown and surrounding areas. This letter has been prepared to provide you with an update of investigations that Bridgestone Australia has been undertaking in relation to groundwater contamination as a result of its historical operations.

The EPA has previously advised that chemical substances have been identified in groundwater and that groundwater/borewater should not be used for any purpose until further notice. Those chemical substances include trichloroethene, which is an industrial solvent and dichloroethene, which is a breakdown product of trichloroethene. These chemicals are most likely associated with historical activities in the area, dating back to when the disposal practices for such chemicals were less regulated than they are today.

These chemicals were used widely in the past by many organisations in the Edwardstown area for metal cleaning, degreasing and dry cleaning. In some instances it is possible that the identified chemicals can rise up from the groundwater into buildings as vapour. This is known as vapour intrusion.

Testing conducted to date has indicated that there may be a minor risk if groundwater were extracted, using a bore or similar, and the water used in your home or garden. Results of most recent investigations indicate there that historical contamination attributable to Bridgestone's historical operations are unlikely to pose an unacceptable inhalation health risk to off-site receptors.

If you have a **bore, fitted with a pump, it should not be used until further notice. Mains (tap) water provided by SA Water is not affected.** For a more detailed map and more information about the assessment, please visit the EPA website at [www.epa.sa.gov.au](http://www.epa.sa.gov.au).

If you do have a groundwater bore on your property, it would be appreciated if you could contact the EPA on the below toll free number as this information will assist the EPA.

If you have any concerns or questions, or if you would like to discuss this letter with an EPA officer, please call the EPA toll free on 1800 729 175 or contact the EPA by email, [epainfo@epa.sa.gov.au](mailto:epainfo@epa.sa.gov.au) ([EPASiteContam@epa.sa.gov.au](mailto:EPASiteContam@epa.sa.gov.au))

Regards,



Bridgestone.

**Auke Roelink** | Group HSE Manager

BRIDGESTONE AUSTRALIA LTD.

P: +61 8 8206 0312 | M: +61 427 977 582