

TO THE RESIDENT

Dear resident

Re: Results from Stage 4 environmental assessment work in Glenelg East

The Environment Protection Authority (EPA) has been overseeing an assessment program at Glenelg East since 2014, to monitor the groundwater and soil vapour for chemicals including trichloroethene (TCE). These chemicals are known to be present in the groundwater beneath a former dry cleaners at 37-41 Cliff Street.

I am writing to advise that the EPA has now received the latest results from the site contamination assessment work in Glenelg East. The results, predicted by computer modelling, indicate that indoor air concentrations of TCE across the residential areas are still considered to be safe, as they are within 'No Action' range (see attached chart "Indoor Air Level Response Range TCE").

A full copy of the report is available on the EPA website (www.epa.sa.gov.au) and follow the links to Site Contamination, Assessment Areas, then Glenelg East).

Groundwater contamination has not been fully delineated to the north and west of the assessment area. During October 2017, the EPA will be installing additional groundwater wells to monitor the groundwater contamination and also to determine the full extent of the plume in the western part of the area. The area is being increased slightly to the west, to include an approximate 140 additional properties (please see map overleaf).

As per previous advice, please do not use groundwater (bore water) for any purpose. Mains water and water from rainwater tanks are not affected. Home grown fruit and vegetables are safe to consume, provided they are not watered using bore water.

If you have any queries or concerns, please do not hesitate to contact the EPA on 1800 729 175 or email EPASiteContam@sa.gov.au for further information.

Yours sincerely



Andrew Prusinski

**MANAGER SITE CONTAMINATION
ENVIRONMENT PROTECTION AUTHORITY**

20 September 2017

Per richiedere una copia di questa lettera in italiano, si prega di telefonare 13 14 50.

Για να ζητήσετε ένα αντίγραφο της παρούσας επιστολής στην ελληνική γλώσσα, παρακαλούμε τηλεφωνήστε στο 13 14 50.

为了要求这封信普通话的副本，请致电13 14 50.

Figure 1: Glenelg East - Stage 5 Environmental Assessment Program

